



- 1: The limit tolerance of the unmarked tolerance is GB/T 1804-92
- 2: All threads should be sprayed for protection
- 3: The edge seams are welded, and polished flat after welding


